

PHENIX WEEKLY PLANNING 10/9/2008 Don Lynch



Technical Support 2008

IR Configuration for remainder of shutdown

October November December January

5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

Station 1 north access now-10/15 (Current Configuration: CM & MMS south WC west

Run Position 10/15 - 10/31 (CM & MMS moved north WC west)

Station 1 south access 11/3-12/12 (MMS moved south WC west)

Station 1 north access 12/15-12/31 (CM moved south, WC west)

East Carriage Install 1/2-1/15 (CM moved north, EC & WC opt.)

Run Position 1/16-1/19
(MMS moved north, EC & WC opt)

Ready for run 9 1/19-2/1
(MuID Collars Installed, EC & WC opt.)
10/9/08

ShutDown Schedule

October November December January

5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

Station 1 north access now-10/15 (Current Configuration: CM & MMS south WC west

Install & test
Sta. 1 N cards now-10/15

Remove Sta 1 N scaffold 10/13-10/15



October November December January

5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

Run Position 10/15 - 10/31 (CM & MMS moved north WC west)

Move CM & MMS north 10/15-10/18 -

MuTrigger S rack ass'y < DONE>

RPC proto rack assy by 10/15

RPC2 proto gas system by 10/31

RPC proto cable by 10/31 routing & support

Install RPC2 prototype 10/20-10/31

PC1 West repairs 10/20-10/31



October November December January 5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

Station 1 south access 11/3-12/12 (MMS moved south WC west)

Move MMS south 11/2

Install sta 1. Scaffolds 11/3-11/7

HBD Installation

MuTrigger FEE 11/10-11/14

Sta 1 S chasis install

Sta 1, 2 & 3 chasis 11/10-11/14

Water & air

Install/test cards 10/2-11/30

sta 2&3 N and sta 1, 2 & 3 S

Install Lead absorber 11/17-11/21

Install FEE S rack platform 11/17-11/21

And racks

FEE S Cabling & Testing 11/24-11/29

MuTr sta 1 5 Decaps 12/1-12/12



October November December January

5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

Station 1 north access 12/15-12/31 (CM moved south, WC west)

Remove Sta 1 S 11/24-12/18 And Sta 2/3 N scaffolds

Move CM south 12/18

Install MMS lampshade 12/18-12/21

Install MMN lampshades12/18-12/31

Shutdown '08 Schedule



Technical Support 2008

October November December January

5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

East Carriage Install 1/2-1/15 (CM moved north, EC & WC opt.)

Install EC 1/2-1/15

Run Position 1/16-1/19 (MMS moved north, EC & WC opt)

Move MMS North 1/16

Ready for run 9 1/19-2/1 (MuID Collars Installed, EC & WC opt.)

DC East/West Repairs 1/16-2/1

Install MuID Collars 1/19-1/21

Pink/Blue/White Sheets 1/16-2/1

Close Shield Wall 126-1/30

Cryo Start Up, Start Physics 2/1-2/18



October November December January 5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

Other On going Tasks

RPC3 Prototype install (by 12/31)
(including assembly at factory,
Moving tunnel shielding, modify
Crystal palace & vapor barrier,
RPC3 install, rack, services & testing)

Fan Tray Mainteance (fill in)

RPC Factory Support

Dark Current test stand

Storage Racks with humid. Cntrl

Prep for 2009 Shutdown (as time permits)

Gas Mixing house UPS by 11/30




October November December January

5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

Rack room electronics, etc.

Build new storage 10/1-11/15 crates

NCC prototype design support HBD support VTX fabrication tooling design VTX installation design FVTX design/engineering support



As Required

PH ** ENIX

Shutdown '08 Electrician Work

- 1. Run Power to new MuTrgr FEE racks on MMS. by 10/31
- 2. Install 120 volt AC power drops into new control room annunciator alarm rack (rack room). Work in progress, to be completed by 10/15.
- 3. Re-wire ToF Rack power distribution bucket in Gas Mixing House. This is to correct minor wiring errors. By 10/31/08
- 4. Install new UPS in Gas mixing house. By 11/30
- 5. Walk down PHENIX Electrical Distribution Panels/Breakers and update changes on the electrical one-line drawings. *Complete by 11/30/08*.
- 6. Install <u>power</u> and <u>signal</u> cable tray (ceiling suspended) for new DCM rack row north of existing DCM racks. To Be Scheduled
- 7. Assist in signal and LV cable installation for MuTr/RPC upgrades as necessary. MuTrgr North Done, MuTrgr South & RPC Prototype to be scheduled
- 8. Repair Duct heaters for Control Room. To Be Scheduled before it gets cold
- 9. Upgrade power capacity of Central Magnet power distribution for future bridge rack loads.
 - a) Remove existing 15KVA transformer and install 45KVA unit.
 - b) Install new (larger size) power cable from rack room to Central Magnet distribution breaker panels.

Lower priority not required for run 9, to be scheduled when manpower available and operations & projects inconvenience are minimized


MuTrig Status

RIKEN/RBRC
Itaru Nakagawa
For
MuTrig Group

All ADTX-FEE cables are installed











Installation Check List

- Miscabling
 - Visible check ✓
 - Data consistency check ✔
- ADTX Performance
 - Slow control ✔
 - Efficiency ✓ → more statistics
 - Fake hit ✓ → only one noisy channel found...
 - Timing ✓ → smeared timing in some channels...
- MuTR FEE Performance
 - Noise → one noisy plane in oct.1
 - Gain → ✓

Noisy Channels










Octant-1, Gap-3 Plane-1&2

Timing Smearing






Man Power



30 ADTX boards arrived yesterday






Plan for this week

- Debugging remaining problems
- Noise hunt with Mike Leitch / next Monday
- Install Thermocouples into station-1
 - Top/Bottom octant

Remaining tasks for completion of North station 1


- Infrastructure
 - Done
- ADTX boards prep
 - All 40 boards installed
- Chain test
 - Noise check
 - Gain check
 - Fake hit rate
 - Efficiency check



History


Date	Run number	MuTRG activity at IR	Other activities
Mar 11	260034	No	Run 8
May 26	260676	No	After run 8, scaffold in?
July 15	261314	No	Decapacitation?
Aug 14	261479	Cable running	Decapacitation?
Sep	261656	Completion of chassis installation	
Sep	261870	Completion of 30-cm cable installation	
Oct 3	261989	Completion of ADTX board installation (LV on)	

July 15 (261314) – May 26 (260676)



No MuTRG activity

Aug 14 (261479) – July 15(261314)




MuTr strip

RMS (ADC ch)

Oct 3 (261989) – Aug 14

(261479)



RMS (ADC ch)






MuTrgr FEE
South Rack
Ready to be
installed
after CM
moves north



MuTrigger FEE South & RPC Prototype Racks






MuTrigger FEE S Rack is done.

Work on these racks is in progress



(Note: DC East shown below; West is similar)



Electronics repair to be accessed in this area after DC is moved east Work permit is in progress.



Entire DC must be moved east ~10"






Bearing rails

Translation Bar (pushing surface) is placed here




Cabling and piping must be carefully evaluated and disconnected or allowed to travel as appropriate







RPC Absorber



We need 80 2x4x8 and 28 2x4xZ, where Z is 13 different lengths of varying quantities between 1-1/2" and 6-3/4"

RFQ placed with CS

J. Scott will deliver 120 2x4x8 rad clean and painted lead bricks, on skid to 1008 by 10/15

Don, Jimmy, Kenny, Carter, John and Mike L. must take TQ-LEAD1 (web course) by 10/15

Checking into lead cutting at SUNYSB

Work permit reg'd

PH ENIX

RPC2 Prototype Installation









RPC prototypes will be ready for installation as follows: RPC3 10/13,

RPC2: 10/20





Dark Current Test Stand components received.



Gap and Module storage plan written and will be made a part of the overall RPC factory plan.



RPC group to dispose of shipping containers and left over equipment to keep storage area uncluttered.





MuTr Decapacitations

Remaining 2008 work: Station 1 South to be done ~ 12/1-12/15 simultaneously with MuTrgr South and RPC absorber installations. Will require Station 1 scaffolding on south side of CM.



(Note: picture at left is mirrorred image of scaffolding in station 1 north.)



Scaffolding Crates




Existing Crates for Sta 2/3N scaffolds are severely rotted and need to be replaced with weather resistant materials.

Sta. 1 scaffolds do not have storage crates. These need to be built of similar materials. All dimensions of crates are available.

PH ENIX

Rack Room Reorganization



Fairly accurate model of the current rack room configuration

Plumbing, HVAC and cable management, items in machine shop and items in laser room omitted

PH ENIX

Safety, Security, etc.

- 1. Cyber Security: now an annual training requirement on all BNL JTA's
- 2. Bldg 912 to be locked. 10 keys: 4 for PHENIX staff, 6 for RPC group those on list see Tracy Blydenburg in 911 to sign for a key.
- 3. Tunnel access for RPC3 installation: anyone with blue RHIC badge, TLD and current RAD Worker 1 training,

Others with GERT training may get a TLD from C-A safety office if they are on the list:

PHENIX: K. Jones, J. LaBounty, M. Lenz, S. Polizzo, F. Toldo, J.Tradeski, C. Biggs, S. Boose, R. Ruggiero, P. Giannotti, E. O'Brien, D. Lynch, R. Pisani

RPC: Rusty Towell, Ralf Seidl, Young Jin, Dave Northacker, Ruizhe Yang, Anselm Vossen, Beau Meredith, Shouyang Hu, Cheng-Yi Chi, David Kleinjahn



Where To Find PHENIX Engineering Info



Links for the weekly planning meeting slides, long term planning, pictures, videos and other technical info can be found on the web site:

http://www.phenix.bnl.gov/WWW/INTEGRATION/ME&Integration/DRL_SSint-page.htm